



- 1) Image of ambient air sampling location at 23<sup>rd</sup> Floor western balcony of BOE building (Subject Building) located at 450 N Street, Sacramento.



- 2) Image of air sampling equipment located within interior of Men's Restroom containment at time of assessment. Note sheetrock removal at area formerly containing sink cabinets.



- 3) Image of reconstructed wall within interior of containment erected at center north hallway fountain chase location area at time of assessment.



- 4) Image of reconstructed wallboard material within southeast hallway containment structures at time of assessment.



- 5) Image of baseboard removal and LCD sampling locations/ID within center containment of north hallway area.



- 6) Close up image of completed LCD sampling/inspection area and repair within mail center containment barrier system at time of assessment.



- 7) Image of air sampling equipment and repaired LCD inspection holes located within Janitor's closet room on south side of building.



- 8) Image of air sampling equipment and repaired LCD inspection holes located within storage room on south west side of building.



- 9) Image of air sampling equipment and repaired LCD inspection areas within LCD-C-11 containment at time of assessment.



- 10) Image of air sampling equipment and repaired LCD inspection areas within LCD-C-6 containment at time of assessment.



11) Image of repaired LCD inspection areas within LCD-C-7 containment at time of assessment.



12) Image of hallway containment entrance and structures of LCD-C-7 at time of assessment.



13) Image of ambient air sampling location at main entrance of BOE building performed at conclusion of interior clearance inspection sampling .